

Marshall Main Street Program

BUILDING SURVEY


Telephone (217) 826-9023

Structure Address: 705 Archdale

Date: 9-7-11

Reference No.: _____

Prepared By: C. Lyman



Name of Present Business: Marshall Family Restaurant

Type of Business: Restaurant

Present Building Owner: Ramiro P & Maria E. Montes

Estimated Construction Date: _____

Original Business or Use: _____

Historic Name: Sam's Restaurant

Any drawings or pictures of early building available: yes

Marshall Main Street Program

BUILDING SURVEY

Telephone (217) 826-9023

Structure Address: 705 Archer

Date: March 11, 2002

Reference No.: _____

Prepared By: Wesley Wells



Name of Present Business: Marshall Family Restaurant

Type of Business: Restaurant

Present Building Owner: _____

Estimated Construction Date: _____

Original Business or Use: _____

Historic Name: _____

Any drawings or pictures of early building available: _____

Marshall Main Street Program

BUILDING SURVEY

Telephone (217) 826-9023

Structure Address: 705 Archer

Date: _____

Reference No.: _____

Prepared By: _____

Location: Archer Ave.

Dimensions: Width _____ Length _____

Corner Building:

Structure Height: 1-Story 2-Story 3-Story

Foundation: Concrete Stone Block/Brick Other Type _____

Exterior Walls:	<input checked="" type="checkbox"/> Brick	<input type="checkbox"/> Stone	<input type="checkbox"/> Vertical Wood Siding
(Above 1st Floor)	<input type="checkbox"/> Horizontal Wood	<input type="checkbox"/> Wood Shingle	<input type="checkbox"/> Stucco
	<input type="checkbox"/> Asphalt Siding	<input type="checkbox"/> Asbestos Siding	<input type="checkbox"/> Artificial Stone
	<input type="checkbox"/> Concrete Block	<input checked="" type="checkbox"/> Aluminum Siding	<input type="checkbox"/> Other

(First Floor)	<input checked="" type="checkbox"/> Brick	<input type="checkbox"/> Stone	<input type="checkbox"/> Vertical Wood Siding
	<input type="checkbox"/> Horizontal Wood	<input type="checkbox"/> Wood Shingle	<input type="checkbox"/> Stucco
	<input type="checkbox"/> Asphalt Siding	<input type="checkbox"/> Asbestos Siding	<input type="checkbox"/> Artificial Stone
	<input type="checkbox"/> Concrete Block	<input checked="" type="checkbox"/> Aluminum Siding	<input type="checkbox"/> Other

Windows	<input checked="" type="checkbox"/> Wood	<input type="checkbox"/> Metal	<input checked="" type="checkbox"/> Double Hung
(Above 1st Floor)	<input type="checkbox"/> Casement (Side Hinge)	<input type="checkbox"/> Sliding	<input type="checkbox"/> Stained, leaded or beveled
	<input type="checkbox"/> Boarded	<input type="checkbox"/> Replaced with brick & filled	<input type="checkbox"/> Other type _____

(First Floor)	<input type="checkbox"/> Wood	<input checked="" type="checkbox"/> Metal	<input type="checkbox"/> Double Hung
	<input type="checkbox"/> Casement (Side Hinge)	<input type="checkbox"/> Sliding	<input checked="" type="checkbox"/> Stained, leaded or beveled
	<input type="checkbox"/> Boarded	<input type="checkbox"/> Replaced with brick & filled	<input type="checkbox"/> Other type _____

Store Front Display Area Rippled or Colored above display Clear above display

Marshall Main Street Program

BUILDING SURVEY

Telephone (217) 826-9023

Structure Address: _____

Date: _____

Reference No.: _____

Prepared By: _____

Awnings	<input type="checkbox"/>	First Floor	<input type="checkbox"/>	Second Floor
Material	<input type="checkbox"/>	Canvas	<input type="checkbox"/>	Aluminum
	<input type="checkbox"/>	Constructed	<input type="checkbox"/>	Wood Shingle
			<input type="checkbox"/>	Roofing Material
Doors	<input type="checkbox"/>	Wood	<input type="checkbox"/>	Metal
	<input type="checkbox"/>	Clear glass in door 30%	<input type="checkbox"/>	Glass
	<input checked="" type="checkbox"/>	Stelite	<input type="checkbox"/>	Clear
	<input checked="" type="checkbox"/>	Tansom	<input type="checkbox"/>	Clear
			<input checked="" type="checkbox"/>	Stained, leaded, or beveled
			<input checked="" type="checkbox"/>	Stained, leaded, or beveled
Cornice	<input checked="" type="checkbox"/>	None	<input type="checkbox"/>	Decorative
	<input type="checkbox"/>	Brackets	<input type="checkbox"/>	Panels, Windows
			<input type="checkbox"/>	Style _____
			<input type="checkbox"/>	Other _____
Main Entrance	<input type="checkbox"/>	Centered	<input checked="" type="checkbox"/>	Off center to right
	<input type="checkbox"/>	Entrance to upper floors	<input type="checkbox"/>	Side entrance (Corner Building)
Unique Ornamental Trim	<input type="checkbox"/>	Bay	<input type="checkbox"/>	Tower or Turret
	<input type="checkbox"/>	Arches	<input type="checkbox"/>	Ornamental Column or Parts
	<input type="checkbox"/>	Decorative Metal Works	<input type="checkbox"/>	Decorative Stone Work
	<input type="checkbox"/>	Outside Stairs	<input type="checkbox"/>	Simple
	<input type="checkbox"/>	Decorative Cross Beam		Decorative Metal
	<input type="checkbox"/>	Decorative Rosettes		Wood

Present Colors: Walls: grey Sidewall _____
 Window trim: white (If corner)
 Doors: glass
 Awning: _____
 Stairs: _____

2nd Floor Use: Used Storage Apt. Office

3rd Floor Use: Used Unused Storage Apt. Office

Marshall Main Street Program

BUILDING SURVEY

Telephone (217) 826-9023

Structure Address: _____

Date: _____

Reference No.: _____

Prepared By: _____

Exterior Renovations: put aluminum siding on building
Description: _____

Estimated Date: _____ Architect or Builder _____

Original Owner: _____

Other Owners:	Dates		1st Floor Use
	From	To	
_____	_____	_____	_____
<u>Frank L. Roads</u>	_____	_____	<u>Grocery Store</u>
<u>Percy Stanfield</u>	<u>1950-</u>	_____	<u>Jonie Cafe</u>
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

2nd & 3rd Floor

Offices or

Residences _____

Marshall Main Street Program

BUILDING SURVEY

Telephone (217) 826-9023

Structure Address: _____

Date: _____

Reference No.: _____

Prepared By: _____

Any original or early interior features still in tact (lights, tin ceiling, etc.)

Integrity of original structure:

- Unaltered
- Slight modification on the building
- Slight modification 1st floor only
- Major modification entire building
- Major modification 1st floor only

Ease to restore original appearance:

Very easy Restore windows, take down awnings, etc.

Moderate *remove aluminum siding, restore windows, restore doorways*

Difficult

Very Difficult

Marshall Main Street Program

BUILDING SURVEY

Telephone (217) 826-9023

Structure Address: _____

Date: _____

Reference No.: _____

Prepared By: _____

Condition of structure:

- Excellent
- Good (No structure problems; needs maintenance)
- Fair (Needs major maintenance & minor structure)
- Poor (Deteriorated & structure problems)

Historical significance

- | | |
|--|--|
| <input type="checkbox"/> Date of origin | <input type="checkbox"/> Occupant |
| <input type="checkbox"/> Architectural style | <input type="checkbox"/> Importance to community |
| <input type="checkbox"/> Architect | <input type="checkbox"/> Importance to streetscape |

Legal Description:

ADDRESS 705 Archer

NAME OF BUSINESS Marshall Family Resurant
~~Tom's Lounge & Dining Room~~

TYPE OF BUSINESS Lounge & Resurant

NUMBER OF STORIES 2

TYPE OF USE IF ANY 2ND FLOOR Storage

3RD FLOOR _____

APPROXIMATE WIDTH OF BUILDING 29 FT.

ON CORNER LOT ? YES _____ NO

NUMBER OF PARKING PLACES IN FRONT 1

NUMBER OF PARKING PLACES ON SIDE 5

UNIQUE FEATURES OF BUILDING:

parking in rear also (8)

COMPLETED BY: Morcroft
Jingly
Breneman

4/97

MA 8/3/2010

Family Restaurant being remodeled

By Gary Strohm
Publisher

A few weeks ago Rudy Montes, owner of the Marshall Family Restaurant, hired Terry Stephens to remodel the kitchen of his restaurant.

The project began two weeks ago. The first step was to remove the equipment. In an effort to keep the bill from

growing too large, Terry enlisted the volunteer help from many of Rudy's friends to clean the equipment.

Terry and his crew then turned their attention to the floor. They found that part of it was concrete while part was wood with a crawspace below. Terry explained that after installing new drains and gas lines, they filled the


crawspaces with fifteen tons of flume fill.

Next, they installed a new floor and FRB wallboard on the walls.

"I want to see the business keep going," said Stephens. "It affects lots of employees and customers."

Rudy's friends have been working hard to clean other areas of the restaurant so that it can reopen sometime later this month.


It will take years for the Montes family to recover from their tragic loss, but it's a comfort to know that they have many caring friends in Marshall.



Brian Brooks, Terry Stephens and Jim Hoopingartner put in place a section of new wall board.
Photo by Gary Strohm.



Several folks volunteered their help at the Minchilli Family Restaurant Monday to clean up equipment and help owner Rudy Montes get the restaurant reopened. Among those helping were (l-r) Stanley Kraemer, Marsha Garner, Jim Hoopingarner, Bill Gaines, Terry Stephens and Gerald Monk. Photo by Gary Strohm. See more details in Friday's Advocate.



THE BRANDENSTILL OPERATING MILL & MINING CO.
INCORPORATED IN THE STATE OF CALIFORNIA
1911

107 Avenue Avenue 105

703

