Marshall Main Street Program

BUILDING SURVEY

Telephone (217) 826-9023

Structure Address: 201 S. Michigan

Date: 3/3/01

Reference No.:

Prepared By: Ashleigh Krischak

Name of Present Business: Marshall City hall

Type of Business: Banking

Present Building Owner: ~~Old National Bank~~ City of Marshall

Estimated Construction Date:

Original Business or Use: ~~Bank~~ City Hall

Historic Name:

Any drawings or pictures of early building available:

Marshall Main Street Program

BUILDING SURVEY Telephone (217) 826-9023

Structure Address: 201 S. Michigan Date: 3/3/01

Reference No.: Prepared By: Ashleigh Krischak

Location: West side of Court house Square ~~South of Court~~ Corner 5th + Archer

Dimensions: Width Length

Corner Building: ☐

Structure Height: ☒ 1-Story ☐ 2-Story ☐ 3-Story

Foundation:	☒	Concrete	☐	Stone	☐	Block/Brick	☐ Other Type
Exterior Walls: (Above 1st Floor) NA	☒	Brick	☐	Stone	☐	Vertical Wood Siding	
	☐	Horizontal Wood	☐	Wood Shingle	☐	Stucco	
	☐	Asphalt Siding	☐	Asbestos Siding	☐	Artificial Stone	
	☐	Concrete Block	☐	Aluminum Siding	☐	Other	
(First Floor)	☒	Brick	☐	Stone	☐	Vertical Wood Siding	
	☐	Horizontal Wood	☐	Wood Shingle	☐	Stucco	
	☐	Asphalt Siding	☐	Asbestos Siding	☐	Artificial Stone	
	☐	Concrete Block	☐	Aluminum Siding	☐	Other	
Windows (Above 1st Floor) NA	☐	Wood	☐	Metal	☒	Double Hung	
	☐	Casement (Side Hinge)	☐	Sliding	☐	Stained, leaded or beveled	
	☐	Boarded	☐	Replaced with brick & filled	☐	Other type Arched	
(First Floor)	☒	Wood	☐	Metal	☐	Double Hung	
	☐	Casement (Side Hinge)	☐	Sliding	☐	Stained, leaded or beveled	
	☐	Boarded	☐	Replaced with brick & filled	☐	Other type	

☐ Store Front Display Area ☐ Rippled or Colored above display ☐ Clear above display

Marshall Main Street Program

BUILDING SURVEY

Telephone (217) 826-9023

Structure Address: 201 S. Michigan Date: 3/3/01

Reference No.: Prepared By: Ashleigh Krischak

Awnings	☒	First Floor		☐	Second Floor	
Material	☐	Canvas	☐	Aluminum		
	☐	Constructed	☒	Wood Shingle	☐	Roofing Material
Doors	☐	Wood	☐	Metal	☒	Glass
	☒	Clear glass in door 30%			☐	Mostly solid wood
	☐	Sidelite	☐	Clear	☐	Stained, leaded, or beveled
	☐	Transom	☐	Clear	☐	Stained, leaded, or beveled
Cornice	☒	None	☐	Decorative	☐	Style
	☐	Brackets	☐	Panels, Windows	☐	Other
Main Entrance	☒	Centered	☐	Off center to right	☐	Off center to left
	☐	Entrance to upper floors	☐	Side entrance (Corner Building)		
Unique Ornamental Trim	☐	Bay	☐	Tower or Turret	☐	Balcony
	☐	Arches	☐	Ornamental Column or Parts	☐	Decorative wooden
	☐	Decorative Metal Works	☐	Decorative Stone Work	☐	Decorative Brick
	☐	Outside Stairs	☐	Simple	☐	Decorative Metal
	☐	Decorative Cross Beam			☐	Wood
	☐	Decorative Rosettes				

Present Colors:

Walls: Red Brick

Sidewall (If corner)

Windowtrim: White

Doors: clear

Awning: White

Stairs: none

2nd Floor Use:	☐	Unused	☐	Storage	☐	Apt.	☐	Office		
3rd Floor Use:	☒	N/A	☐	Unused	☐	Storage	☐	Apt.	☐	Office

Marshall Main Street Program

BUILDING SURVEY

Telephone (217) 826-9023

Structure Address:_____ Date:_____

Reference No.:_____ Prepared By:_____

Any original or early interior features still in tact (lights, tin ceiling, etc.)

_____

_____

_____

_____

Integrity of original structure:

- ☐ Unaltered
- ☐ Slight modification on the building
- ☐ Slight modification 1st floor only
- ☐ Major modification entire building
- ☐ Major modification 1st floor only

Ease to restore original appearance:

☐ Very easy Restore windows, take down awnings, etc.

_____

_____

☐ Moderate _____

_____

_____

☐ Difficult _____

_____

_____

☐ Very Difficult _____

_____

_____