Marshall Main Street Program

BUILDING SURVEY

Telephone (217) 826-9023

Structure Address: 220 South 6th St.

Date: August 29, 1998

Reference No.:

Prepared By: Karen Cown

Name of Present Business: Shawler Law Offices

Type of Business: Law office

Present Building Owner: Omar Shawler

Estimated Construction Date:

Original Business or Use:

Historic Name:

Any drawings or pictures of early building available:

Marshall Main Street Program

BUILDING SURVEY

Telephone (217) 826-9023

Structure Address: 220 S. 6th

Date: 3/16/00

Reference No.:

Prepared By: Harley Bennet.

Location:

Dimensions: Width 22' Length

Corner Building: ☐

Structure Height: ☒ 1-Story ☐ 2-Story ☐ 3-Story

Foundation:	☐	Concrete	☐	Stone	☐	Block/Brick	☐ Other Type
Exterior Walls:	☒	Brick	☐	Stone	☐	Vertical Wood Siding	
(Above 1st Floor)	☐	Horizontal Wood	☐	Wood Shingle	☐	Stucco	
	☐	Asphalt Siding	☐	Asbestos Siding	☐	Artificial Stone	
	☐	Concrete Block	☐	Aluminum Siding	☐	Other	
(First Floor)	☒	Brick	☐	Stone	☐	Vertical Wood Siding	
	☐	Horizontal Wood	☐	Wood Shingle	☐	Stucco	
	☐	Asphalt Siding	☐	Asbestos Siding	☐	Artificial Stone	
	☐	Concrete Block	☐	Alnminum Siding	☐	Other	
Windows	☐	Wood	☐	Metal	☒	Double Hung	
(Above 1st Floor)	☐	Casement (Side Hinge)	☐	Sliding	☐	Stained, leaded or beveled	
	☐	Boarded	☐	Replaced with brick & filled	☐	Other type	
(First Floor)	☐	Wood	☐	Metal	☒	Double Hung	
	☐	Casement (Side Hinge)	☐	Sliding	☐	Stained, leaded or beveled	
	☐	Boarded	☐	Replaced with brick & filled	☐	Other type	

☐ Store Front Display Area ☐ Rippled or Colored above display ☐ Clear above display

ADDRESS 220 So 6th

NAME OF BUSINESS Shawler Law Office

TYPE OF BUSINESS Atty. - at - law

NUMBER OF STORIES 1

TYPE OF USE IF ANY 2ND FLOOR —

3RD FLOOR —

APPROXIMATE WIDTH OF BUILDING 36 FT.

ON CORNER LOT ? _____ YES ✓ NO

NUMBER OF PARKING PLACES IN FRONT 2

NUMBER OF PARKING PLACES ON SIDE —

UNIQUE FEATURES OF BUILDING:

New construction; brick (1940's)

COMPLETED BY : Pat Barth

Marshall Main Street Program

BUILDING SURVEY

Telephone (217) 826-9023

Structure Address: 220 S. 6th

Date: 3/16/00

Reference No.:

Prepared By: Harley Bennett

Awnings	☐		First Floor	☐	Second Floor		
Material	☐	Canvas	☐	Aluminum			
	☐	Constructed	☐	Wood Shingle	☐	Roofing Material	
Doors	☐	Wood	☒	Metal	☐	Glass	
	☒	Clear glass in door 30%			☐	Mostly solid wood	
	☐	Sidelite	☐	Clear	☐	Stained, leaded, or beveled	
	☐	Transom	☐	Clear	☐	Stained, leaded, or beveled	
Cornice	☒	None	☐	Decorative	☐	Style	
	☐	Brackets	☐	Panels, Windows	☐	Other	
Main Entrance	☒	Centered	☐	Off center to right	☐	Off center to left	
	☐	Entrance to upper floors	☐	Side entrance (Corner Building)			
Unique Ornamental Trim	☐	Bay	☐	Tower or Turret	☐	Balcony	
	☐	Arches	☐	Ornamental Column or Parts	☐	Decorative wooden	
	☐	Decorative Metal Works	☐	Decorative Stone Work	☐	Decorative Brick	
	☐	Outside Stairs	☐	Simple	☐	Decorative Metal	
	☐	Decorative Cross Beam			☐	Wood	
	☐	Decorative Rosettes					

Present Colors:

Walls: multicolored Brick

Sidewall (If corner)

Windowtrim:

Doors:

Awning:

Stairs:

2nd Floor Use:	☐	Unused	☐	Storage	☐	Apt.	☐	Office	
3rd Floor Use:	☐	N/A	☐	Unused	☐	Storage	☐	Apt.	☐ Office

Marshall Main Street Program

BUILDING SURVEY

Telephone (217) 826-9023

Structure Address: 220 S. 6th

Date: 3/16/00

Reference No.:

Prepared By: Harley Bennett

Any original or early interior features still in tact (lights, tin ceiling, etc.)

Integrity of original structure:

- ☐ Unaltered
- ☒ Slight modification on the building
- ☐ Slight modification 1st floor only
- ☐ Major modification entire building
- ☐ Major modification 1st floor only

Ease to restore original appearance:

- ☐ Very easy — Restore windows, take down awnings, etc.
- ☒ Moderate — Building was originally flat roofed. Ceiling have been lowered and space over entrance door and windows was filled in with decorative stone.
- ☐ Difficult
- ☐ Very Difficult